



## Authorization

Precision Concrete Cutting (PCC) removes only those trip hazards specifically requested by customers, and therefore makes no guarantee or representation that the property is free of trip hazards after the contract is completed. Also, it is the customers' responsibility to provide proper access and PCC assumes no liability for trip hazards that cannot be identified or repaired due to parked vehicles or other obstacles preventing safe and practical access. In this case, PCC will return one extra time to complete the repairs and will charge a fee of up to \$250 per mobilization. Also, it is recognized that after completion of the contract, trip hazards may and frequently do continue to move naturally over time due to roots, water, freezing, pipes, and other natural or man-made causes. PCC is not responsible for movement or changes in the sidewalks and is not liable for any related claims, losses, damages, or liabilities thereto pertaining. Also, if sidewalk assessment is more than 12-month-old at the time of signature of the contract, there will be a 10% price increase allowance to provision for possible increases of trip hazard measurements.

Pricing is valid for 90-days and is based on the volume of work represented in the proposal. Should you decide to reduce the volume of work by more than 20%, a unit price increase of 10% may apply. Payment terms of invoices are 15 days unless otherwise stated. Contracts greater than \$25,000 are invoiced monthly.

*By signing below, I attest that I have read the above statements, understand them completely, and agree. By my signature and authorization, PCC is approved to complete the work detailed in this proposal in accordance with PCC's schedule. Payment of PCC's invoice(s) will confirm that I have inspected PCC's work and that it was performed to my satisfaction.*

**Date:** \_\_\_\_\_ **P.O.#:** \_\_\_\_\_

**Signature Authorized Agent:** \_\_\_\_\_

**Print Name & Title:** \_\_\_\_\_

**Is it OK to perform work on Saturdays?** Yes \_\_\_\_ / No \_\_\_\_

**Is work on Saturdays required to ensure safety and avoid disruption?** Yes \_\_\_\_ / No \_\_\_\_

<b>REF #:</b>	2022.09.22.A.HJ	<b><u>Precision Concrete Cutting</u></b>
<b>DATE:</b>		CSLB #1032474
<b>CUSTOMER:</b>	Glenbrook Middle School	
<b>C/O:</b>	Mt Diablo Unified School District	Headquarters: 417 Harrison Street
<b>CONTACT:</b>	Melanie Koslow	Oakland, CA 94607
<b>ADDRESS:</b>	1936 Carlotta Dr.	SF Peninsula: 335 Beach Road
<b>CITY / ZIP:</b>	Concord, CA 94519-1397	Burlingame, CA 94010
<b>PHONE:</b>	(925) 596-0446	Sacramento: 1425 N Market Blvd #9
<b>PROPERTY LOCATION:</b>	2351 Olivera Rd Concord CA 94520	Sacramento, CA 95834
<b>TOTAL COST:</b>	<b>\$55,615.20</b>	Heather Jimison hjimison@PCCnorcal.com Cell - 916-607-0447

This document is intended only for the use of the individual or entity to which it is addressed. The contents are proprietary and confidential and contains information that is both privileged and confidential under applicable California law. If you have received or are in possession of this document, you are hereby notified that any dissemination, use, distribution, or copying of this information is strictly prohibited. Any violation will be strictly enforced and litigated under the laws of the State of California.





REF #	2022.09.22.A.HJ	<b>Precision Concrete Cutting</b>
CUSTOMER:	Glenbrook Middle School	CSLB #1032474
C/O:	Mt Diablo Unified School District	
CONTACT:	Melanie Koslow	Heather Jimison
ADDRESS:	1936 Carlotta Dr.	hjimison@PCCnorcal.com
CITY / ZIP:	Concord, CA 94519-1397	916-607-0447 - Cell
PHONE:	(925) 596-0446	650-240-3866 - Fax
PROPERTY LOCATION:	2351 Olivera Rd Concord CA 94520	

**SIDEWALK REPAIR DETAILED REPORT**






**Total Cost**  
**\$55,615.20**

**LEGEND:** WW=Walkway SW=Sidewalk CSW=City Sidewalks DW=Driveway GB=Gutter Bed R&R=Remove and Replace (not repaired) ATTN=Attention (not repaired) GAP-M=Gap 1/2"-1" wide GAP-L=Gap 1"-2" wide OG=Old Grind OC=Old Cut PATCH=Asphalt or Concrete Patch ASPCUT=Asphalt Cut






*This document is intended only for the use of the individual or entity to which it is addressed. The contents are proprietary and contain information that is both privileged and confidential under applicable California law. If you have received or are in possession of this document, you are hereby notified that any dissemination, use, distribution, or copying of this information is strictly prohibited. Any violation will be strictly enforced and litigated under the laws of the State of California.*

No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
1	3	1	5.5	SW 2351 Olivera Rd : Past Apron. At Rocketship Academy Sign. At Crack LCUT.		\$82.80
2	2	0	4	SW 2351 Olivera Rd : Past Apron. At Rocketship Academy Sign. At Crack LCUT. XCUT		\$30.00
3	2	0	2.5	SW 2351 Olivera Rd : Past Apron. At Rocketship Academy Sign. At Crack. XCUT LCUT		\$18.60
4	2	0	4	SW 2351 Olivera Rd : Past Apron. At Rocketship Academy Sign. At Crack. LCUT		\$30.00

No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
5	2	0	3.5	SW 2351 Olivera Rd : Past Apron. By Rocketship Academy Sign. At Crack.		\$26.40
6	4	1	8	SW 2351 Olivera Rd : At Rocketship Academy Sign. At Crack. LCUT		\$150.00
7	3	1	3	SW 2351 Olivera Rd : At Rocketship Academy Sign. At Crack. LCUT		\$45.00
8	4	0	3.5	SW 2351 Olivera Rd : At Rocketship Academy Sign. ASPCUT		\$52.80
9	6	0	23	SW 2351 Olivera Rd : At Rocketship Academy Sign. ASPCUT		\$517.80

No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
10	7	0	11	SW 2351 Olivera Rd : Past Rocketship Academy Sign. LCUT		\$288.60
11	5	0	4.5	SW 2351 Olivera Rd : Past Rocketship Academy Sign. ATCURB. LCUT		\$84.60
12	2	0	3.5	SW 2351 Olivera Rd : Past Rocketship Academy Sign.		\$26.40
13	2	0	5.5	SW 2351 Olivera Rd : Before Handicap Parking. At Crack.		\$41.40
14	2	1	1	SW 2351 Olivera Rd : Before Handicap Parking. At Crack. LCUT		\$11.40

No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
15	2	1	1	SW 2351 Olivera Rd : Before Handicap Parking. At Crack. LCUT		\$11.40
16	2	0	4	SW 2351 Olivera Rd : Before Handicap Parking. At Crack.		\$30.00
17	2	0	3	SW 2351 Olivera Rd : Before Handicap Parking. By 6ft apart Sign.		\$22.80
18	7	0	24.5	SW 2351 Olivera Rd : Before Handicap Parking. By 6ft apart Sign. ASPCUT		\$643.20
19	2	0	2	SW 2351 Olivera Rd : At 6ft apart Sign. LCUT		\$15.00

No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
20	3	1	9.5	SW 2351 Olivera Rd : At 6ft apart Sign. At Crack. LCUT		\$142.80
21	2	2	3	SW 2351 Olivera Rd : At 6ft apart Sign. At Crack. LCUT		\$45.00
22	2	0	3.5	SW 2351 Olivera Rd : At 6ft apart Sign. At Crack. LCUT		\$26.40
23	3	0	2.5	SW 2351 Olivera Rd : At 6ft apart Sign. At Crack. LCUT		\$28.20
24	2	0	3.5	SW 2351 Olivera Rd : At 6ft apart Sign. LCUT		\$26.40

No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
25	6	0	27	SW 2351 Olivera Rd : Past 6ft apart Sign. CURBCUT LCUT		\$607.80
26	3	0	2.5	SW 2351 Olivera Rd :		\$28.20
27	5	0	8.5	SW 2351 Olivera Rd : Before Handicap Parking. At Crack.		\$159.60
28	3	0	3.5	SW 2351 Olivera Rd : Before Handicap Parking. At Crack.		\$39.60
29	3	0	2	SW 2351 Olivera Rd : Before Handicap Parking. At Crack.		\$22.80

No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
30	3	3	1.5	SW 2351 Olivera Rd : Before Handicap Parking. At Crack. LCUT.		\$33.60
31	2	2	2	SW 2351 Olivera Rd : Before Handicap Parking. At Crack. LCUT.		\$30.00
32	4	2	1.5	SW 2351 Olivera Rd : Before Handicap Parking. At Crack. LCUT.		\$33.60
33	2	0	2.5	SW 2351 Olivera Rd : By Handicap Parking. At Crack.		\$18.60
34	7	0	6	SW 2351 Olivera Rd : By Handicap Parking. By 6ft Apart Sign. Unfinished OC. XCUT		\$157.80



No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
35	2	0	3	SW 2351 Olivera Rd : By Handicap Parking. By 6ft Apart Sign. XCUT		\$22.80
36	5	0	10.5	SW 2351 Olivera Rd : By Handicap Parking. Past 6ft Apart Sign. ASCUT.		\$196.80
37	8	0	25.5	SW 2351 Olivera Rd : At Handicap Parking. ASCUT.		\$765.00
38	2	1	4	SW 2351 Olivera Rd : At Handicap Parking. At Crack.		\$45.00
39	10	0	1.5	SW 2351 Olivera Rd : At Handicap Parking. At Crack. OC. LCUT		\$56.40

No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
40	6	0	6	SW 2351 Olivera Rd : At Handicap Parking. Unfinished OC. LCUT XCUT		\$135.00
41	2	0	2	SW 2351 Olivera Rd : At Handicap Parking. XCUT		\$15.00
42	2	1	18.5	SW 2351 Olivera Rd : Past Handicap Parking. At Crack. LCUT.		\$208.20
43	2	1	3.5	SW 2351 Olivera Rd : Past Handicap Parking. At Crack. LCUT.		\$39.60
44	4	0	2.5	SW 2351 Olivera Rd : Past Handicap Parking. LCUT.		\$37.80

No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
45	3	0	2.5	SW 2351 Olivera Rd : Past Handicap Parking. At Crack. LCUT.		\$28.20
46	4	0	7.5	SW 2351 Olivera Rd : Past Handicap Parking. Past 6ft Apart Sign. ATCURB.		\$112.80
47	2	0	3	SW 2351 Olivera Rd : Past Handicap Parking. At Bench. At Crack.		\$22.80
48	5	4	15.5	SW 2351 Olivera Rd : Past Handicap Parking. At Bench. LCUT		\$523.20
49	4	0	3.5	SW 2351 Olivera Rd : Past Handicap Parking. ATCURB LCUT		\$52.80

No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
50	4	0	7.5	SW 2351 Olivera Rd : By ww to Middle School. ATCURB LCUT.		\$112.80
51	4	1	5	SW 2351 Olivera Rd : By ww to Middle School. LCUT.		\$93.60
52	2	0	4	SW 2351 Olivera Rd : By ww to Middle School.		\$30.00
53	2	1	9.5	SW 2351 Olivera Rd : At ww to Middle School.		\$106.80
54	5	2	5	SW 2351 Olivera Rd : At ww to Middle School. At Ramp.		\$131.40

No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
55	2	0	4	SW 2351 Olivera Rd : Pastt ww to Middle School. By 6ft Apart Sign. LCUT		\$30.00
56	3	1	3	SW 2351 Olivera Rd : Pastt ww to Middle School. By 6ft Apart Sign. At Crack. LCUT		\$45.00
57	2	1	1	SW 2351 Olivera Rd : Pastt ww to Middle School. By 6ft Apart Sign. At Crack. LCUT		\$11.40
58	4	2	2	SW 2351 Olivera Rd : Pastt ww to Middle School. By 6ft Apart Sign. At Crack. LCUT		\$45.00
59	2	0	2.5	SW 2351 Olivera Rd : Pastt ww to Middle School. By 6ft Apart Sign. At Crack.		\$18.60






No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
60	2	0	4.5	SW 2351 Olivera Rd : Past ww 6ft Apart Sign.		\$33.60
61	2	0	7.5	SW 2351 Olivera Rd : Past ww 6ft Apart Sign.		\$56.40
62	2	0	2	SW 2351 Olivera Rd : Past ww 6ft Apart Sign. By Glenbrook Middle School Sign.		\$15.00
63	3	1	3	SW 2351 Olivera Rd : Across Glenbrook Middle School Sign. Atcrack. LCUT		\$45.00
64	2	1	3	SW 2351 Olivera Rd : Across Glenbrook Middle School Sign. Atcrack. LCUT		\$33.60






No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
65	4	0	12	SW 2351 Olivera Rd : Across Glenbrook Middle School Sign. Atcrack. LCUT		\$180.00
66	3	0	10	SW 2351 Olivera Rd : Across Glenbrook Middle School Sign.		\$112.80
67	3	1	8	SW 2351 Olivera Rd : Across Glenbrook Middle School Sign. At 6ft apart Sign.		\$120.00
68	7	0	4.5	SW 2351 Olivera Rd : Across Glenbrook Middle School Sign. At 6ft apart Sign.		\$118.20
69	2	1	9	SW 2351 Olivera Rd : Across Glenbrook Middle School Sign. By 6ft apart Sign.		\$101.40

No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
70	4	1	13.5	SW 2351 Olivera Rd : Past Glenbrook Middle School Sign. Past 6ft apart Sign.		\$253.20
71	9	0	20.5	SW 2351 Olivera Rd : Past Glenbrook Middle School Sign. Past 6ft apart Sign. CURBCUT.		\$691.80
72	6	1	16.5	SW 2351 Olivera Rd : Past Glenbrook Middle School Sign. Past 6ft apart Sign.		\$433.20
73	2	0	4.5	SW 2351 Olivera Rd : 6ft apart Sign. At Crack. LCUT.		\$33.60
74	2	0	4.5	SW 2351 Olivera Rd : 6ft apart Sign. LCUT.		\$33.60



No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
75	2	0	6.5	SW 2351 Olivera Rd : By High Voltage Box.		\$48.60
76	2	2	0.5	SW 2351 Olivera Rd : At High Voltage Box. At Crack. LCUT		\$7.80
77	3	2	0.5	SW 2351 Olivera Rd : At High Voltage Box. At Crack. LCUT		\$9.60
78	3	2	0.5	SW 2351 Olivera Rd : At High Voltage Box. LCUT		\$9.60
79	3	0	1	SW 2351 Olivera Rd : At High Voltage Box. LCUT		\$11.40

No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
80	3	1	6	SW 2351 Olivera Rd : At High Voltage Box. LCUT		\$90.00
81	2	0	9	SW 2351 Olivera Rd : By High Voltage Box. By Yield Sign.		\$67.80
82	2	0	3	SW 2351 Olivera Rd : Past High Voltage Box. At Yield Sign. At Crack. XCUT		\$22.80
83	3	0	3	SW 2351 Olivera Rd : Past High Voltage Box. At Yield Sign. XCUT LCUT		\$33.60
84	4	1	3	SW 2351 Olivera Rd : Past High Voltage Box. At Yield Sign. At Crack. LCUT		\$56.40




No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
85	4	0	7.5	SW 2351 Olivera Rd : At Yield Sign. ATCURB. LCUT		\$112.80
86	3	3	0.5	SW 2351 Olivera Rd : By Yield Sign. At 6ft Apart Sign. At Crack. LCUT		\$11.40
87	2	2	0.5	SW 2351 Olivera Rd : By Yield Sign. At 6ft Apart Sign. At Crack. LCUT		\$7.80
88	3	2	0.5	SW 2351 Olivera Rd : By Yield Sign. At 6ft Apart Sign. At Crack. LCUT		\$9.60
89	2	0	3.5	SW 2351 Olivera Rd : At Yield Sign. Past 6ft Apart Sign.		\$26.40

No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
90	2	0	2.5	SW 2351 Olivera Rd : Past Yield Sign. At Crack. XCUT		\$18.60
91	3	0	5	SW 2351 Olivera Rd : Past Yield Sign. At Crack. XCUT JUMP		\$56.40
92	0	0	0	ATTN SW 2351 Olivera Rd : High Voltage Box LIFTED.		DO NOT FIX
93	3	0	10	WW 2351 Olivera Rd : At ww to middle school. At Art Room Door.		\$112.80
94	2	0	12	WW 2351 Olivera Rd : At Room 129.		\$90.00

No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
95	2	0	1.5	WW 2351 Olivera Rd : Past Vault Room.		\$11.40
96	2	0	7	WW 2351 Olivera Rd : Past Office Door.		\$52.80
97	3	2	9	WW 2351 Olivera Rd : Past Office Door.		\$168.60
98	2	0	1.5	WW 2351 Olivera Rd : Past Office Door.		\$11.40
99	3	0	6	WW 2351 Olivera Rd : By room 106.		\$67.80

No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
100	2	0	8	WW 2351 Olivera Rd : At room 106.		\$60.00
101	6	1	7	? WW 2351 Olivera Rd : At Restrooms.		\$183.60
102	2	0	3.5	? WW 2351 Olivera Rd : At ww to Gated Black Top. Across Resturant.		\$26.40
103	6	0	8	? WW 2351 Olivera Rd : At gated Quad.		\$180.00
104	9	0	8.5	? WW 2351 Olivera Rd : At gated Quad. At 100 wing Gate.		\$286.80





No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
105	7	0	19	? WW 2351 Olivera Rd : At gated Quad. Past ww to Blacktop. LCUT		\$498.60
106	4	1	11	? WW 2351 Olivera Rd : At gated Quad. Past ww to Blacktop. LCUT		\$206.40
107	2	0	8.5	? WW 2351 Olivera Rd : At gated Quad. Past ww to Blacktop. LCUT. XCUT		\$63.60
108	2	0	7	? WW 2351 Olivera Rd : At gated Quad. Past ww to Blacktop. XCUT		\$52.80
109	4	2	9.5	? WW 2351 Olivera Rd : At gated Quad. At ww to CSW. JUMP		\$213.60

No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
110	2	0	4.5	WW 2351 Olivera Rd : Past Womens restroom. Before room 203.		\$33.60
111	2	0	5	WW 2351 Olivera Rd : At Library Door.		\$37.80
112	3	0	2	WW 2351 Olivera Rd : At Rocket Ship Academy. Before Room 507. LCUT		\$22.80
113	5	0	4.5	WW 2351 Olivera Rd : At Rocket Ship Academy. Before Room 507. LCUT		\$84.60
114	3	0	3.5	WW 2351 Olivera Rd : At Rocket Ship Academy. Before Room 507. At Sewer.		\$39.60



No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
115	3	0	6.5	WW 2351 Olivera Rd : Across Room 507. At Asphalt.		\$73.20
116	4	0	11	WW 2351 Olivera Rd : Across Kitchen Room. ASPCUT. XCUT		\$165.00
117	8	0	1.5	WW 2351 Olivera Rd : Across Kitchen Room. At Asphalt. XCUT		\$45.00
118	3	0	7	WW 2351 Olivera Rd : Before Multipurpose Room. At Lunch Table. XCUT		\$78.60
119	7	0	40.5	WW 2351 Olivera Rd : Across Multipurpose Room. PastbLunch Table. XCUT. LCUT		\$1,063.20

No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
120	7	2	19	WW 2351 Olivera Rd : Past Multipurpose Room. LCUT		\$641.40
121	5	0	9.5	WW 2351 Olivera Rd : Past Multipurpose Room. At Gate to Middle school. LCUT		\$178.20
122	5	0	1.5	WW 2351 Olivera Rd : Past Multipurpose Room. At Gate to Middle school. LCUT		\$28.20
123	3	0	8	WW 2351 Olivera Rd : At Gate to Middle school. At Crack.		\$90.00
124	2	0	2	WW 2351 Olivera Rd : At Gate to Middle school. At Door. At Crack. LCUT		\$15.00

No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
125	3	2	3	WW 2351 Olivera Rd : At Gate to Middle school. At Door. LCUT		\$56.40
126	3	2	6	WW 2351 Olivera Rd : Gate to Middle school. Across Door.		\$112.80
127	4	0	8.5	WW 2351 Olivera Rd : Before Childrens Restroom. At ww to classrooms. LCUT		\$127.80
128	2	1	8.5	WW 2351 Olivera Rd : Before Childrens Restroom. At ww to classrooms. LCUT		\$95.40
129	3	0	5	WW 2351 Olivera Rd : At ww to classrooms. LCUT		\$56.40

No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
130	2	0	7	WW 2351 Olivera Rd : At ww to classrooms. At Water Lid.		\$52.80
131	3	0	2.5	WW 2351 Olivera Rd : At ww to classrooms. Before Benches.		\$28.20
132	3	0	8	WW 2351 Olivera Rd : At ww to classrooms. Before Benches.		\$90.00
133	3	2	8	WW 2351 Olivera Rd : At ww to classrooms. By Benches.		\$150.00
134	3	1	8	WW 2351 Olivera Rd : At ww to classrooms. At Benches.		\$120.00


No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
135	2	0	6.5	WW 2351 Olivera Rd : At ww to classrooms. At Benches.		\$48.60
136	2	0	3.5	WW 2351 Olivera Rd : At ww to classrooms. At Benches. XCUT.		\$26.40
137	3	0	5.5	WW 2351 Olivera Rd : At ww to classrooms. At Benches. XCUT.		\$61.80
138	7	2	8.5	WW 2351 Olivera Rd : At ww to classrooms. Past Benches. Unfinished OC.		\$286.80
139	0	0	0	ATTN WW 2351 Olivera Rd : At ww to classrooms. Side Of Slab Chipped.		DO NOT FIX


No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
140	3	1	8.5	WW 2351 Olivera Rd : Before Room 05.		\$127.80
141	5	0	4	WW 2351 Olivera Rd : Before Room 05.		\$75.00
142	3	0	4	WW 2351 Olivera Rd : At Hallway. Before Room 05. LCUT		\$45.00
143	3	0	4	WW 2351 Olivera Rd : At Hallway. Before Room 05. LCUT		\$45.00
144	3	0	6.5	WW 2351 Olivera Rd : By Hallway. Before Room 05.		\$73.20

No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
145	3	1	9	WW 2351 Olivera Rd : At Hallway. Before Room 05. LCUT		\$135.00
146	3	0	6.5	WW 2351 Olivera Rd : At Hallway. Before Room 05. LCUT		\$73.20
147	2	0	3	WW 2351 Olivera Rd : By Hallway. Before Room 05. By Storm Drain.		\$22.80
148	4	1	2	WW 2351 Olivera Rd : By Hallway. By Room 05. At Storm Drain. LCUT		\$37.80
149	7	5	2	WW 2351 Olivera Rd : By Hallway. By Room 05. At Storm Drain. LCUT		\$90.00






No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
150	5	2	2	WW 2351 Olivera Rd : By Hallway. By Room 05. At Storm Drain. LCUT		\$52.80
151	2	0	5	WW 2351 Olivera Rd : By Hallway. By Room 05. At Storm Drain.		\$37.80
152	3	0	4	WW 2351 Olivera Rd : By Hallway. Before Room 205. By Storm Drain.		\$45.00
153	4	0	7.5	WW 2351 Olivera Rd : At Room 205.		\$112.80
154	4	0	5.5	WW 2351 Olivera Rd : Across Room 205. XCUT		\$82.80



No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
155	3	0	3.5	WW 2351 Olivera Rd : Across Room 205. XCUT		\$39.60
156	8	0	7	WW 2351 Olivera Rd : Across Room 205. At Benches.		\$210.00
157	4	4	8.5	WW 2351 Olivera Rd : Oast Room 205. At Benches. LCUT		\$255.00
158	2	0	3	WW 2351 Olivera Rd : Oast Room 205. Past Benches. LCUT		\$22.80
159	3	2	8.5	WW 2351 Olivera Rd : Before Room 206. Before Benches.		\$159.60


No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
160	3	0	5.5	WW 2351 Olivera Rd : By Room 206. LCUT		\$61.80
161	3	0	5.5	WW 2351 Olivera Rd : By Room 206. LCUT		\$61.80
162	2	0	5.5	WW 2351 Olivera Rd : By Room 206.		\$41.40
163	4	0	7	WW 2351 Olivera Rd : At Room 206. LCUT		\$105.00
164	2	0	4.5	WW 2351 Olivera Rd : At Room 206. LCUT		\$33.60

No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
165	9	1	9.5	WW 2351 Olivera Rd : Past Room 206. OC.		\$356.40
166	7	0	6.5	WW 2351 Olivera Rd : Past Room 206. OC.		\$170.40
167	5	2	8.5	WW 2351 Olivera Rd : Past Room 206. Unfinished OC. LCUT		\$223.20
168	2	0	4.5	WW 2351 Olivera Rd : Past Room 206. LCUT		\$33.60
169	2	0	3	WW 2351 Olivera Rd : Before Room 207.		\$22.80

No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
170	3	0	5.5	WW 2351 Olivera Rd : Past Room 206. Before Room 207.		\$61.80
171	2	0	5	WW 2351 Olivera Rd : At Room 207.		\$37.80
172	6	0	17	WW 2351 Olivera Rd : At Room 207.		\$382.80
173	3	0	6	WW 2351 Olivera Rd : Across Room 207. At Bench.		\$67.80
174	7	0	7.5	WW 2351 Olivera Rd : Pastv Room 207. Past Bench. LCUT		\$196.80

No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
175	7	0	4	WW 2351 Olivera Rd : Pastv Room 207. Past Bench. By Storm Drain. LCUT		\$105.00
176	6	2	8.5	WW 2351 Olivera Rd : Before Room 208 Past Bench. By Storm Drain.		\$255.00
177	7	3	2	WW 2351 Olivera Rd : By Room 208. At Storm Drain. LCUT		\$75.00
178	5	3	2	WW 2351 Olivera Rd : By Room 208. At Storm Drain. LCUT		\$60.00
179	6	3	2	WW 2351 Olivera Rd : By Room 208. At Storm Drain. LCUT		\$67.80

No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
180	6	5	2	WW 2351 Olivera Rd : By Room 208. At Storm Drain. LCUT		\$82.80
181	2	0	7	WW 2351 Olivera Rd : Across Room 208. By Storm Drain.		\$52.80
182	5	0	7	WW 2351 Olivera Rd : Across Room 208. Past Storm Drain. XCUT		\$131.40
183	2	0	1.5	WW 2351 Olivera Rd : Across Room 208. Past Storm Drain. XCUT		\$11.40
184	2	0	5	WW 2351 Olivera Rd : Across Room 208. LCUT		\$37.80

No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
185	3	0	5.5	WW 2351 Olivera Rd : Across Room 208. LCUT		\$61.80
186	2	0	9	WW 2351 Olivera Rd : By Room 208.		\$67.80
187	3	0	11	WW 2351 Olivera Rd : Before Room 208.		\$123.60
188	3	0	4	WW 2351 Olivera Rd : At Room 208. XCUT		\$45.00
189	3	0	4	WW 2351 Olivera Rd : At Room 208. XCUT		\$45.00






No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
190	2	0	6.5	WW 2351 Olivera Rd : Past Room 208.		\$48.60
191	2	0	3.5	WW 2351 Olivera Rd : Before Room 209.		\$26.40
192	9	4	8.5	WW 2351 Olivera Rd : Before Room 209. LCUT		\$414.60
193	10	4	8.5	WW 2351 Olivera Rd : By Room 209. Before Benches. LCUT		\$446.40
194	16	0	7	WW 2351 Olivera Rd : By Room 209. By Benches. LCUT XCUT		\$420.00








No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
195	0	0	0	RR WW 2351 Olivera Rd : Across Room 209. SLAB OVER 3inches.		DO NOT FIX
196	3	0	4.5	WW 2351 Olivera Rd : Past Room 209.		\$50.40
197	3	0	4.5	WW 2351 Olivera Rd : Past Room 209. Past Benches.		\$50.40
198	4	0	6	WW 2351 Olivera Rd : Past Room 209. Past Benches. XCUT		\$90.00
199	3	0	2.5	WW 2351 Olivera Rd : Past Room 209. Past Benches. XCUT		\$28.20

No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
200	4	0	4	WW 2351 Olivera Rd : Past Room 209. Past Benches.		\$60.00
201	12	2	8.5	WW 2351 Olivera Rd : Before Across Room 209. At Bench		\$446.40
202	7	1	8.5	WW 2351 Olivera Rd : Before Across Room 209. At Bench		\$255.00
203	4	0	2.5	WW 2351 Olivera Rd : Across Room 209. At Bench. At Crack. XCUT		\$37.80
204	12	0	6	WW 2351 Olivera Rd : Across Room 209. At Bench. At Crack. XCUT. LCUT		\$270.00






No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
205	13	8	4	WW 2351 Olivera Rd : Across Room 209. At Bench. LCUT		\$315.00
206	7	0	5	WW 2351 Olivera Rd : Across Room 209. Past Bench. XCUT.		\$131.40
207	6	0	4	WW 2351 Olivera Rd : Across Room 209. Past Bench. XCUT.		\$90.00
208	7	0	6.5	WW 2351 Olivera Rd : Across Room 209. Before Across room 208. LCUT		\$170.40
209	6	1	8.5	WW 2351 Olivera Rd : Across Room 209. Before Across room 208. LCUT		\$223.20

No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
210	5	1	8.5	WW 2351 Olivera Rd : Before Across room 208. LCUT		\$191.40
211	3	0	5.5	WW 2351 Olivera Rd : Before Across room 208. LCUT. XCUT		\$61.80
212	5	0	3.5	WW 2351 Olivera Rd : By Across room 208. XCUT. LCUT		\$65.40
213	3	3	8.5	WW 2351 Olivera Rd : By Across room 208. LCUT		\$191.40
214	2	0	4.5	WW 2351 Olivera Rd : Across room 208. XCUT		\$33.60

No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
215	2	0	4.5	WW 2351 Olivera Rd : Across room 208. XCUT LCUT		\$33.60
216	2	0	5	WW 2351 Olivera Rd : Across room 208. LCUT XCUT		\$37.80
217	4	0	4	WW 2351 Olivera Rd : Across room 208. At AC Units. XCUT		\$60.00
218	3	0	6.5	WW 2351 Olivera Rd : Across room 208. At AC Units. By Storm Drain.		\$73.20
219	2	0	6	WW 2351 Olivera Rd : Across room 208. At AC Units. By Storm Drain. XCUT		\$45.00

No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
220	5	0	2.5	WW 2351 Olivera Rd : Across room 208.At AC Units. Past Storm Drain. XCUT		\$46.80
221	9	0	6	WW 2351 Olivera Rd : Across room 208.At AC Units.		\$202.80
222	2	0	3	WW 2351 Olivera Rd : Befire Across room 207. At AC Units.		\$22.80
223	3	0	3.5	WW 2351 Olivera Rd : Befire Across room 207. At AC Units.		\$39.60
224	8	0	6	WW 2351 Olivera Rd : Across Across room 207. At Bench. XCUT		\$180.00

No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
225	3	0	3	WW 2351 Olivera Rd : Across Across room 207. At Bench. XCUT		\$33.60
226	2	0	7	WW 2351 Olivera Rd : Across Across room 207. By Bench.		\$52.80
227	4	1	8.5	WW 2351 Olivera Rd : Across Across room 207. Pass Bench.		\$159.60
228	3	0	6	WW 2351 Olivera Rd : Across Across room 206. At Bench.		\$67.80
229	4	0	6.5	WW 2351 Olivera Rd : Across Across room 206. At Bench. By Sewer Lid. XCUT		\$97.80


No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
230	3	0	2.5	WW 2351 Olivera Rd : Across Across room 206. At Bench. By Sewer Lid. XCUT		\$28.20
231	3	0	4	WW 2351 Olivera Rd : Before Across Across room 205. XCUT		\$45.00
232	2	0	4.5	WW 2351 Olivera Rd : Before Across Across room 205. XCUT		\$33.60
233	3	0	2.5	WW 2351 Olivera Rd : By Across Across room 205. At Crack. XCUT		\$28.20
234	3	0	4	WW 2351 Olivera Rd : By Across Across room 205. At Crack. XCUT LCUT		\$45.00








No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
235	12	0	4.5	WW 2351 Olivera Rd : By Across room 205. LCUT XCUT		\$202.80
236	2	0	4	WW 2351 Olivera Rd : By Across room 205. XCUT		\$30.00
237	3	0	6.5	WW 2351 Olivera Rd : Across room 205. At Bench.		\$73.20
238	4	0	7	WW 2351 Olivera Rd : Across room 205. At Bench. LCUT		\$105.00
239	4	1	8.5	WW 2351 Olivera Rd : Across room 205. At Bench. By Storm Drain. LCUT		\$159.60




No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
240	2	0	5.5	WW 2351 Olivera Rd : Across room 205. Past Bench. By Storm Drain.		\$41.40
241	3	2	8	WW 2351 Olivera Rd : Past Across room 205. Past Storm Drain. At Sewer Lid. JUMP		\$150.00
242	4	1	8.5	WW 2351 Olivera Rd : At Hallway before room 700.		\$159.60
243	5	2	10.5	WW 2351 Olivera Rd : Before room 700. At Lunch Table.		\$275.40
244	5	2	13.5	WW 2351 Olivera Rd : Past room 700.		\$354.60





No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
245	3	0	7	WW 2351 Olivera Rd : Before Room 303.		\$78.60
246	12	0	8	WW 2351 Olivera Rd : Before Room 303. At Storm Drain. OC		\$360.00
247	5	0	7.5	WW 2351 Olivera Rd : Before Room 303. Past Storm Drain.		\$140.40
248	9	0	7.5	WW 2351 Olivera Rd : By Room 303. Past Storm Drain. Unfinished OC. XCUT		\$253.20
249	3	0	2	WW 2351 Olivera Rd : By Room 303. XCUT LCUT		\$22.80

No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
250	5	0	9.5	WW 2351 Olivera Rd : By Room 303. LCUT		\$178.20
251	3	0	3	WW 2351 Olivera Rd : At Room 303. LCUT		\$33.60
252	3	0	7.5	WW 2351 Olivera Rd : At Room 303. LCUT		\$84.60
253	7	0	16.5	WW 2351 Olivera Rd : At Room 303.		\$433.20
254	4	0	3	WW 2351 Olivera Rd : Past Room 303. At Room 304. XCUT		\$45.00

No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
255	3	0	5	WW 2351 Olivera Rd : At Room 304. XCUT		\$56.40
256	5	3	8	WW 2351 Olivera Rd : At Room 304. LCUT		\$240.00
257	4	0	3.5	WW 2351 Olivera Rd : Past Room 304. LCUT XCUT		\$52.80
258	9	0	5.5	WW 2351 Olivera Rd : Past Room 304. At Bench. XCUT		\$185.40
259	9	0	12.5	WW 2351 Olivera Rd : Past Room 304. Before Room 305. LCUT		\$421.80



No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
260	4	0	4.5	WW 2351 Olivera Rd : At Room 305. LCUT		\$67.80
261	2	0	5.5	WW 2351 Olivera Rd : By Room 305. At Bench.		\$41.40
262	7	2	7.5	WW 2351 Olivera Rd : Across Room 305. At Bench. LCUT		\$253.20
263	7	4	8.5	WW 2351 Olivera Rd : Across Room 305. At Bench. LCUT		\$350.40
264	3	1	9	WW 2351 Olivera Rd : At Room 305. LCUT		\$135.00






No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
265	5	0	3	WW 2351 Olivera Rd : At Room 305. LCUT		\$56.40
266	14	0	125	WW 2351 Olivera Rd : At Room 305.		\$6,562.80
267	2	0	3	WW 2351 Olivera Rd : Across Room 305. At Crack. XCUT		\$22.80
268	2	0	2	WW 2351 Olivera Rd : Across Room 305. At Crack. XCUT LCUT		\$15.00
269	2	0	3	WW 2351 Olivera Rd : Across Room 305. At Crack. LCUT		\$22.80






No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
270	8	7	8.5	WW 2351 Olivera Rd : Past Across Room 305. At Benchz Unfinished OC.		\$478.20
271	4	0	5.5	WW 2351 Olivera Rd : Before Room 306. At Bench By Storm Drain. XCUT.		\$82.80
272	6	0	3	WW 2351 Olivera Rd : Before Room 306. At Bench By Storm Drain. XCUT. LCUT		\$67.80
273	8	4	2.5	WW 2351 Olivera Rd : Before Room 306. At Storm Drain. LCUT		\$112.80
274	8	6	2.5	WW 2351 Olivera Rd : Before Room 306. At Storm Drain. LCUT		\$131.40



No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
275	3	3	2.5	WW 2351 Olivera Rd : Before Room 306. At Storm Drain. LCUT		\$56.40
276	2	0	5	WW 2351 Olivera Rd : Before Room 306. Past Storm Drain.		\$37.80
277	3	0	7	WW 2351 Olivera Rd : Across Room 306.		\$78.60
278	9	3	8.5	WW 2351 Olivera Rd : Across Room 306. OC		\$382.80
279	3	0	7.5	WW 2351 Olivera Rd : Past Room 306. By Bench		\$84.60

No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
280	2	0	5.5	WW 2351 Olivera Rd : Before Room 307. At Bench. XCUT		\$41.40
281	3	0	3.5	WW 2351 Olivera Rd : Before Room 307. At Bench. XCUT		\$39.60
282	3	0	7.5	WW 2351 Olivera Rd : By Room 307. By Bench.		\$84.60
283	3	0	7	WW 2351 Olivera Rd : Across Room 307. At Bench.		\$78.60
284	3	2	8	WW 2351 Olivera Rd : Across Room 307. Past Bench.		\$150.00




No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
285	4	1	8.5	WW 2351 Olivera Rd : Past Room 307.		\$159.60
286	3	0	5	WW 2351 Olivera Rd : By Room 308. At Bench. XCUT		\$56.40
287	2	0	3	WW 2351 Olivera Rd : By Room 308. At Bench. XCUT LCUT		\$22.80
288	5	0	6.5	WW 2351 Olivera Rd : By Room 308. At Bench. LCUT		\$121.80
289	4	0	5	WW 2351 Olivera Rd : Across Room 308. At Bench. XCUT		\$75.00

No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
290	2	0	2	WW 2351 Olivera Rd : Across Room 308. By Bench. XCUT		\$15.00
291	3	0	1.5	WW 2351 Olivera Rd : Past Across Room 308. Past Bench.		\$16.80
292	4	0	6.5	WW 2351 Olivera Rd : Past Room 308.		\$97.80
293	2	0	7.5	WW 2351 Olivera Rd : Past Room 308. Before ww to other Classrooms.		\$56.40
294	0	0	0	RR WW 2351 Olivera Rd : Past Room 308. At ww to other Classrooms. SLAB DAMAGED		DO NOT FIX

No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
295	3	0	3	WW 2351 Olivera Rd : At ww to other Classrooms. Across room 209		\$33.60
296	4	0	8.5	WW 2351 Olivera Rd : Across room 209. XCUT		\$127.80
297	3	0	1.5	WW 2351 Olivera Rd : Across room 209. XCUT		\$16.80
298	3	0	2	WW 2351 Olivera Rd : Across room 209. JUMP		\$22.80
299	3	0	1.5	WW 2351 Olivera Rd : Before Room 308. XCUT		\$16.80





No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
300	9	0	6.5	WW 2351 Olivera Rd : Before Room 308. XCUT		\$219.60
301	5	1	8.5	WW 2351 Olivera Rd : Before Room 308. LCUT		\$191.40
302	3	2	8.5	WW 2351 Olivera Rd : Before Room 308. LCUT		\$159.60
303	4	0	6	WW 2351 Olivera Rd : Across Room 308. By Bench. XCUT		\$90.00
304	7	0	3	WW 2351 Olivera Rd : Across Room 308. By Bench. XCUT LCUT		\$78.60





No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
305	5	0	15	WW 2351 Olivera Rd : Across Room 308. By Bench. LCUT		\$281.40
306	3	2	4.5	WW 2351 Olivera Rd : Across Room 308. Across Bench.		\$84.60
307	2	0	2	WW 2351 Olivera Rd : Across Room 308. Across Bench.		\$15.00
308	2	0	4.5	WW 2351 Olivera Rd : Across Room 308. Across Bench.		\$33.60
309	2	0	6	WW 2351 Olivera Rd : Across Room 308. By Bench.		\$45.00

No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
310	3	0	1	WW 2351 Olivera Rd : Across Room 308. At Bench.		\$11.40
311	4	0	3	WW 2351 Olivera Rd : Across Room 308. Across Bench.		\$45.00
312	7	0	4.5	WW 2351 Olivera Rd : Across Room 308. At Bench. Before room 307.		\$118.20
313	2	0	2	WW 2351 Olivera Rd : Across Room 308. Past Bench. Before room 307.		\$15.00
314	3	0	6.5	WW 2351 Olivera Rd : Past Room 308. Past Bench. Before room 307. XCUT		\$73.20













No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
315	3	0	2	WW 2351 Olivera Rd : Past Room 308. Past Bench. Before room 307. XCUT		\$22.80
316	3	0	2.5	WW 2351 Olivera Rd : By Across Room 307.		\$28.20
317	3	0	7	WW 2351 Olivera Rd : Across Room 307.		\$78.60
318	4	0	4.5	WW 2351 Olivera Rd : Across Before Room 307.		\$67.80
319	2	0	2	WW 2351 Olivera Rd : Across By Room 307. LCUT		\$15.00

No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
320	4	0	4.5	WW 2351 Olivera Rd : Across By Room 307. LCUT		\$67.80
321	2	0	5.5	WW 2351 Olivera Rd : Across By Room 307. At Crack. LCUT XCUT		\$41.40
322	2	0	3	WW 2351 Olivera Rd : Across By Room 307. At Crack. XCUT. LCUT		\$22.80
323	6	0	5	WW 2351 Olivera Rd : Across Room 307. LCUT. XCUT		\$112.80
324	3	0	3	WW 2351 Olivera Rd : Across Room 307. XCUT		\$33.60

No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
325	3	0	1	WW 2351 Olivera Rd : Across Room 307. By Bench. XCUT LCUT		\$11.40
326	5	5	8	WW 2351 Olivera Rd : Across Room 307. At Bench. LCUT		\$300.00
327	7	4	5	WW 2351 Olivera Rd : Across Room 307. Unfinished OC.		\$206.40
328	2	0	2.5	WW 2351 Olivera Rd : Across Room 307.		\$18.60
329	6	2	10	WW 2351 Olivera Rd : At ww to back Gate. Unfinished OC.		\$300.00

No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
330	0	0	0	ATTN WW 2351 Olivera Rd : At ww to back Gate. HOLE		DO NOT FIX
331	5	0	2.5	WW 2351 Olivera Rd : At ww to back Gate. At Asphalt. XCUT		\$46.80
332	2	0	6.5	WW 2351 Olivera Rd : At ww to back Gate. ASPCUT. XCUT. JUMP		\$48.60
333	0	0	0	ATTN WW 2351 Olivera Rd : Across room 307. At ww to Gate. WOOD SEAM RAISED		DO NOT FIX
334	4	0	4	WW 2351 Olivera Rd : Across room 307. At Bench. XCUT.		\$60.00

No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
335	3	0	3	WW 2351 Olivera Rd : Across room 307. At Bench. XCUT.		\$33.60
336	5	0	5.5	WW 2351 Olivera Rd : Across Past room 307. At Bench.		\$103.20
337	3	0	3.5	WW 2351 Olivera Rd : Across Past room 307. At Bench.		\$39.60
338	2	0	5.5	WW 2351 Olivera Rd : Across room 306. Past Bench.		\$41.40
339	3	0	3	WW 2351 Olivera Rd : Across room 306. Past Bench.		\$33.60


No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
340	3	0	4.5	WW 2351 Olivera Rd : Across room 306. Before Bench.		\$50.40
341	2	0	7	WW 2351 Olivera Rd : Across room 306. Before Bench. LCUT		\$52.80
342	2	0	6	WW 2351 Olivera Rd : Across room 306. By Bench. LCUT		\$45.00
343	2	0	6.5	WW 2351 Olivera Rd : Across room 306. At Bench.		\$48.60
344	3	0	6	WW 2351 Olivera Rd : Across past room 306. At Bench. LCUT		\$67.80






No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
345	5	2	8.5	WW 2351 Olivera Rd : Across past room 306. At Bench. Unfinished OC. LCUT		\$223.20
346	4	0	6.5	WW 2351 Olivera Rd : Across room 305. Past Bench. LCUT		\$97.80
347	8	5	8.5	WW 2351 Olivera Rd : Across room 305. Past Bench. OC. LCUT		\$414.60
348	2	0	7.5	WW 2351 Olivera Rd : Across room 305. Before Bench.		\$56.40
349	0	0	0	ATTN WW 2351 Olivera Rd : Across room 305. At Bench. WOOD SEAM LIFTED.		DO NOT FIX






No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
350	2	0	6	WW 2351 Olivera Rd : Across room 305. At Bench.		\$45.00
351	6	1	8.5	WW 2351 Olivera Rd : Across Before room 304. At Bench.		\$223.20
352	2	0	2	WW 2351 Olivera Rd : Across room 304. Past Bench.		\$15.00
353	0	0	0	ATTN WW 2351 Olivera Rd : Across room 304. WOOD SEAM LIFTED.		DO NOT FIX
354	2	0	5	WW 2351 Olivera Rd : Across room 304. Before Bench.		\$37.80







No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
355	2	0	1.5	WW 2351 Olivera Rd : Past Room 303. At Hallway.		\$11.40
356	3	0	5.5	WW 2351 Olivera Rd : At ww before Room 403. At Asphalt. XCUT		\$61.80
357	4	0	11.5	WW 2351 Olivera Rd : By Room 403. ASPCUT. XCUT		\$172.80
358	2	0	3.5	WW 2351 Olivera Rd : At Room 403. At Asphalt. XCUT		\$26.40
359	6	6	1.5	WW 2351 Olivera Rd : At Room 403. At Electric Box. ASPCUT. LCUT		\$67.80

No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
360	5	5	1	WW 2351 Olivera Rd : At Room 403. At Electric Box. ASPCUT. LCUT		\$37.80
361	4	2	1.5	WW 2351 Olivera Rd : At Room 403. At Electric Box. ASPCUT. LCUT		\$33.60
362	6	4	1	WW 2351 Olivera Rd : At Room 403. At Electric Box. ASPCUT. LCUT		\$37.80
363	3	0	3.5	WW 2351 Olivera Rd : At Room 403. Past Electric Box. At Asphalt.		\$39.60
364	4	0	7.5	WW 2351 Olivera Rd : At Room 404. ASPCUT.		\$112.80

No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
365	5	0	14.5	WW 2351 Olivera Rd : Past Room 404. ASPCUT. XCUT		\$271.80
366	2	0	3.5	WW 2351 Olivera Rd : By Room 405. At Asphalt. XCUT		\$26.40
367	5	0	19	WW 2351 Olivera Rd : At Room 405. At Asphalt. XCUT.		\$356.40
368	3	0	10.5	WW 2351 Olivera Rd : Before Room 404. ASPCUT. XCUT.		\$118.20
369	3	2	9	WW 2351 Olivera Rd : At Room 404. At ASPCUT.		\$168.60

No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
370	3	0	19	WW 2351 Olivera Rd : Past Room 404. At ASPCUT.		\$213.60
371	4	0	5	WW 2351 Olivera Rd : At Room 900. ASPCUT.		\$75.00
372	2	1	3.5	WW 2351 Olivera Rd : At Room 900. ASPCUT. LCUT		\$39.60
373	6	1	14	WW 2351 Olivera Rd : At Room 900. ASPCUT. LCUT		\$367.80
374	4	0	12	WW 2351 Olivera Rd : At Room 901. ASPCUT.		\$180.00

No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
375	2	0	4	WW 2351 Olivera Rd : Past Room 901. ASCUT.		\$30.00
376	2	1	5	WW 2351 Olivera Rd : At Room 902. ASCUT.		\$56.40
377	6	2	5	WW 2351 Olivera Rd : At ww to room 903. At Asphalt. LCUT		\$150.00
378	12	0	4	WW 2351 Olivera Rd : At ww to room 903. At Asphalt. LCUT XCUT.		\$180.00
379	3	0	5	WW 2351 Olivera Rd : At ww to room 903. ASCUT. XCUT. JUMP		\$56.40

No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
380	2	1	2.5	WW 2351 Olivera Rd : Past room 903. At Blacktop. At Sewer Lid. ASPCUT.		\$28.20
381	2	1	3.5	WW 2351 Olivera Rd : Past boys Restroom. Before Playground. At Storm Drain.		\$39.60
382	3	1	3.5	WW 2351 Olivera Rd : Behind Boys Restroom Bld. By High Voltage Box. ASPCUT.		\$52.80
383	3	0	5	WW 2351 Olivera Rd : Before Girls Restroom. ASPCUT.		\$56.40
384	2	2	2	WW 2351 Olivera Rd : By Locker Room. Before Gate to Parking. At Storm Drain. ASPCUT.		\$30.00

No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
385	2	0	2	WW 2351 Olivera Rd : By Church Before Gate to Parking. At Storm Drain. ASPCUT.		\$15.00
386	0	0	0	ATTN WW 2351 Olivera Rd : By Locker room. Before Gate to Parking. HOLE.		DO NOT FIX
387	4	1	2	WW 2351 Olivera Rd : Before Boys Locker Room. At Storm Drain. ASPCUT.		\$37.80
388	5	1	2.5	WW 2351 Olivera Rd : Before across Girls Locker Room. At Storm Drain. ASPCUT. LCUT.		\$56.40
389	3	1	2.5	WW 2351 Olivera Rd : Before across Girls Locker Room. At Storm Drain. ASPCUT. LCUT.		\$37.80



No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
390	4	2	2.5	WW 2351 Olivera Rd : Before across Girls Locker Room. At Storm Drain. ASCP. LCUT.		\$56.40
391	3	1	2.5	WW 2351 Olivera Rd : Before across Girls Locker Room. At Storm Drain. ASCP. LCUT.		\$37.80
392	13	11	4.5	WW 2351 Olivera Rd : At Detector Cap. ASCP.		\$405.00
393	3	0	12.5	WW 2351 Olivera Rd : Past Electric Box. ASCP.		\$140.40
394	5	2	4	WW 2351 Olivera Rd : At Utility Box. ASCP.		\$105.00




No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
395	7	4	1.5	WW 2351 Olivera Rd : At Electric Box. ASCP. LCUT.		\$61.80
396	7	4	1	WW 2351 Olivera Rd : At Electric Box. ASCP. LCUT.		\$41.40
397	5	3	1.5	WW 2351 Olivera Rd : At Electric Box. ASCP. LCUT.		\$45.00
398	3	0	0.5	WW 2351 Olivera Rd : At Storm Drain. ASCP.		\$5.40
399	3	1	1.5	WW 2351 Olivera Rd : Before Gym Door. At Electric Box. ASCP. LCUT		\$22.80






No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
400	3	2	2	WW 2351 Olivera Rd : Before Gym Door. At Electric Box. ASPCUT. LCUT		\$37.80
401	3	1	1.5	WW 2351 Olivera Rd : Before Gym Door. At Electric Box. ASPCUT. LCUT		\$22.80
402	2	0	1	WW 2351 Olivera Rd : Before Gym Door. At Electric Box. ASPCUT. LCUT		\$7.80
403	3	2	1.5	WW 2351 Olivera Rd : Before Gym Door. At Electric Box. ASPCUT. LCUT		\$28.20
404	2	1	1.5	WW 2351 Olivera Rd : Before Gym Door. At Electric Box. ASPCUT. LCUT		\$16.80

No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
405	3	0	1	WW 2351 Olivera Rd : By Gym Door. At Electric Box. ASPCUT. LCUT		\$11.40
406	3	1	5	WW 2351 Olivera Rd : At Gym Door. At Asphalt. LCUT		\$75.00
407	3	0	6.5	WW 2351 Olivera Rd : At Gym Door. At Asphalt. LCUT		\$73.20
408	2	0	4.5	WW 2351 Olivera Rd : At Gym Door. At Asphalt.		\$33.60
409	3	0	2	CSW 2351 Olivera Rd : Past Crosswalk.		\$22.80

No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
410	3	2	4.5	CSW 2351 Olivera Rd : At Storm Drain.		\$84.60
411	2	0	2	CSW 2351 Olivera Rd : Finish Storm Drain.		\$15.00
412	3	0	3	CSW 2351 Olivera Rd : Before Soeed Limit.		\$33.60
413	2	1	4	CSW 2351 Olivera Rd : By Speed Limit.		\$45.00
414	2	0	1.5	CSW 2351 Olivera Rd : Past Speed Limit. XCUT		\$11.40





No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
415	2	0	2.5	CSW 2351 Olivera Rd : Past Speed Limit. XCUT		\$18.60
416	4	1	4	CSW 2351 Olivera Rd : Before Apron to school parking lot.		\$75.00
417	4	2	4	CSW 2351 Olivera Rd : Before Apron to school parking lot.		\$90.00
418	2	1	4	CSW 2351 Olivera Rd : Before Apron to school parking lot.		\$45.00
419	3	1	4	CSW 2351 Olivera Rd : At Apron to school parking lot.		\$60.00

No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
420	2	0	6	CSW 2351 Olivera Rd : At Apron to school parking lot.		\$45.00
421	7	5	4.5	CSW 2351 Olivera Rd : At Apron to school parking lot. OC		\$202.80
422	2	1	4	CSW 2351 Olivera Rd : Past Apron to school parking lot. At Yield Sign.		\$45.00
423	2	0	3	CSW 2351 Olivera Rd : By Apron to school parking lot. Past Fire Hydrant.		\$22.80
424	3	1	4	CSW 2351 Olivera Rd : Past SW To Glenbrook Middle. At Crosswalk.		\$60.00

No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
425	3	0	2.5	CSW 2351 Olivera Rd : Past SW To Glenbrook Middle. Past Crosswalk.		\$28.20
426	2	1	4	CSW 2351 Olivera Rd : Past Crosswalk.		\$45.00
427	2	0	3	CSW 2351 Olivera Rd : At Bus Stop. At High Voltage Box.		\$22.80
428	5	0	3	CSW 2351 Olivera Rd : Past High Voltage Box.		\$56.40
429	3	0	3	CSW 2351 Olivera Rd : Past High Voltage Box.		\$33.60

No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
430	7	0	3.5	CSW 2351 Olivera Rd : At Tree.		\$91.80
431	2	0	2	CSW 2351 Olivera Rd : At Tree. At Crack.		\$15.00
432	4	3	10	WW 2351 Olivera Rd : Past Tree. WW To School Gate.		\$262.80
433	5	4	4	CSW 2351 Olivera Rd : By WW to echool Gate. At Patch.		\$135.00
434	2	1	4	CSW 2351 Olivera Rd :p. Past WW to echool Gate. .		\$45.00



No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
435	8	0	12	ADDON WW 2351 Olivera Rd : Parking Lot Of School. At CSW. ASPCUT		\$360.00
436	7	0	106.5	ADDON WW 2351 Olivera Rd : Parking Lot Of School. At CSW. ASPCUT		\$2,795.40
437	6	0	68.5	ADDON WW 2351 Olivera Rd : Parking Lot Of School. At CSW. ASPCUT		\$1,541.40
438	3	9	ADDON WW 2351 Olivera Rd : Parking Lot Of School. At CSW. ASPCUT		\$101.40	