

R 99155
License # 768589

East Bay Pool Service

To: CPHS
Attn: Robert Greathouse
From: East Bay Pool Service
Re: Pool Heater replacement

Rob

As we discussed the other day when I brought over some example heater burners from another pools "Wilder" The damage that has occurred in the past to both CPHS heaters is recurring on the #2 heater. This issue has been discovered to be a common issue with these Pentair Powermax heaters. As well as many other issues, such as piping leaks, circulating pump failures, flow sensor failures, all of which your heaters at CPHS have had. Currently the #2 heater is inoperable due to the Burner failures.

My recommendation is to replace the #2 heater with a Lochinvar CPN1442 pool heater. We have found the Lochinvar heaters to be far more reliable than the Pentair, Laars, and Raypak heaters.

Scope of work:


Remove and dispose of through recycling the existing #2 pool heater, Install new heater CPN1442 in its place, and make operational.

Heater and Materials for Installation	\$ 26,454.00
Installation	\$ 8,500.00

Thanks
Sam Terry, East Bay Pool

Notes

Lead time is 18 days after order is placed
installation can take up to a week


Rob Greathouse 518/17
Director

Effect on pool operation will be minimal, maybe one day that we will need to close the pool if that