



Terms and Conditions of Engagement and Authorization to Commence Work

The undersigned (the "Customer") hereby engages Precision Concrete Cutting ("PCC") and agrees to the terms and conditions set forth below. PCC removes only those trip hazards specifically requested by customers, and therefore makes no guarantee or representation that the property is free of trip hazards after the contract is completed. In addition, PCC only performs certain trip hazard repairs. Among other things, PCC does not remove and replace sidewalk slabs (R&Rs) and does not repair certain ATTNs (e.g. utility boxes). Furthermore, to preserve clients' budget, PCC typically does not perform any repair at and around any sidewalk slabs that require to be replaced. Also, it is recognized that after completion of the contract, trip hazards may and frequently do continue to move naturally over time due to roots, water, freezing, pipes, and other natural or man-made causes. PCC is not responsible for movement or changes in the sidewalks and is not liable for any related claims, losses, damages, or liabilities thereto pertaining.

It is the customers' responsibility to provide proper access and PCC assumes no liability for trip hazards that cannot be identified or repaired due to parked vehicles or other obstacles preventing safe and practical access. In this case, PCC will return one extra time to complete the repairs and will charge a fee of up to \$250 per mobilization. Similarly, if repair work cannot be performed on the agreed upon working dates or needs to be rescheduled less than 3 business days before any agreed upon working date, PCC will charge a rescheduling fee of up to 10% of the contract value.

Pricing is valid for 90-days and is based on the volume of work represented in the proposal. If the sidewalk assessment is more than 12-month-old at the time of signature of the contract, there will be a 10% price increase allowance to provision for possible increases of trip hazard measurements. Should you decide to reduce the volume of work by more than 20%, a unit price increase of 10% may apply. Payment terms of invoices are 15 days unless otherwise stated. Contracts greater than \$25,000 are invoiced monthly.

By signing below, I attest that I have read the above statements, understand them completely, and agree. I confirm that I am duly authorized to sign this agreement on behalf of the Customer. By my signature, PCC is approved to complete the work detailed in this proposal in accordance with PCC's schedule and pricing below and attached. Also, Payment of PCC's invoice(s) will confirm that I have inspected PCC's work and that it was performed to my satisfaction.

Date: _____ P.O.#: _____

Signature Authorized Agent: _____

Print Name & Title: _____

Is it OK to perform work on Saturdays? Yes ____ / No ____

Is work on Saturdays required to ensure safety and avoid disruption? Yes ____ / No ____

REF #:	2023.11.8.A.HJ	Precision Concrete Cutting
DATE:		CSLB #1032474
CUSTOMER:	Mount Diablo High School - Mount Diablo Unified School District	
C/O:	Mount Diablo Unified Schc	Headquarters: 417 Harrison Street
CONTACT:	Melanie Koslow	Oakland, CA 94607
ADDRESS:	1936 Carlotta Drive	SF Peninsula: 335 Beach Road
CITY / ZIP:	Concord, Ca 94519	Burlingame, CA 94010
PHONE:	(925) 596-0446	Sacramento: 1425 N Market Blvd #9
PROPERTY LOCATION:	2450 Grant Street, Concord, Ca 94520	Sacramento, CA 95834
TOTAL COST:	\$37,075.35	Heather Jimison
DISCOUNT:	TIPS CONTRACT PRICING	hjimison@PCCnorcal.com
		Cell - 916-607-0447

This document is intended only for the use of the individual or entity to which it is addressed. The contents are proprietary and confidential and contains information that is both privileged and confidential under applicable California law. If you have received or are in possession of this document, you are hereby notified that any dissemination, use, distribution, or copying of this information is strictly prohibited. Any violation will be strictly enforced and litigated under the laws of the State of California.






REF #	2023.11.8.A.HJ	Precision Concrete Cutting
CUSTOMER:	Mount Diablo High School - Mount Diablo Unified School	CSLB #1032474
C/O:	Mount Diablo Unified School District	
CONTACT:	Melanie Koslow	Heather Jimison
ADDRESS:	1936 Carlotta Drive	hjimison@PCCnorcal.com
CITY / ZIP:	Concord, Ca 94519	916-607-0447 - Cell
PHONE:	(925) 596-0446	650-240-3866 - Fax
PROPERTY LOCATION:	2450 Grant Street, Concord, Ca 94520	






SIDEWALK REPAIR DETAILED REPORT

Total Cost
\$37,075.35

LEGEND: WW=Walkway SW=Sidewalk CSW=City Sidewalks DW=Driveway GB=Gutter Bed R&R=Remove and Replace (not repaired)
ATTN=Attention (not repaired) GAP-M=Gap 1/2"-1" wide GAP-L=Gap 1"-2" wide OG=Old Grind OC=Old Cut PATCH=Asphalt or Concrete

This document is intended only for the use of the individual or entity to which it is addressed. The contents are proprietary and contain information that is both privileged and confidential under applicable California law. If you have received or are in possession of this document, you are hereby notified that any dissemination, use, distribution, or copying of this information is strictly prohibited. Any violation will be strictly enforced and litigated under the laws of the State of California.

No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
1	3	0	4	SW 2450 Grant St bld Science : by handicap parking area at Ac units area by ramp MVCAR		\$48.75
2	2	0	17.5	SW bld Science : pass handicap parking area at ramp area by service gate area MVCAR ASPCUT		\$142.35
3	2	0	6	SW bld Science : at service gate area at ramp area pass Science bld before Music bld MVCAR		\$48.75






No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
4	2	1	6	SW bld Science : at service gate area at ramp area pass Science bld before Music bld MVCAR		\$73.45
5	4	0	16	SW bld Music : pass service gate area pass ramp area by Music bld MVCAR CURBCUT		\$260.00
6	2	0	5.5	SW bld Music : pass service gate area pass ramp area by Music bld MVCAR		\$44.85
7	6	0	27	SW bld Music : pass service gate area pass ramp area by Music bld MVCAR CURBCUT		\$658.45
8	4	0	7.5	SW bld Music : before student entrance gate by Music bld across from green donation box MVCAR CURBCUT		\$122.20






No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
9	4	0	5	SW bld Music : before student entrance gate by Music bld across from green donation box MVCAR CURBCUT		\$81.25
10	3	0	3	SW bld Music : by student entrance gate by white fire hydrant across from green donation box MVCAR		\$36.40
11	2	0	3.5	SW bld Music : by student entrance gate at white fire hydrant across from green donation box MVCAR		\$28.60
12	2	1	4	SW bld Music : by student entrance gate at white fire hydrant across from green donation box MVCAR DANGER		\$48.75
13	2	1	4	SW bld Music : pass student entrance gate at sewer lid by green donation box MVCAR DANGER		\$48.75






No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
14	2	0	2.5	SW bld Music : pass student entrance gate at sewer lid by green donation box MVCAR DANGER CRACK		\$20.15
15	2	0	15.5	SW bld Music : at green donation box pass sewer lid at staff parking area MVCAR		\$126.10
16	4	0	21	SW bld Music : at green donation box pass sewer lid by staff parking area MVCAR PARALLEL CUT		\$341.25
17	2	0	2	SW bld Music : at green donation box pass sewer lid by staff parking area MVCAR XCUT		\$16.25
18	2	0	2	SW bld Music : at green donation box pass sewer lid by staff parking area MVCAR XCUT		\$16.25



No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
19	3	0	2.5	SW bld Music : by green donation box pass sewer lid by staff parking area MVCAR XCUT OG		\$30.55
20	3	0	1.5	SW bld Music : by green donation box pass sewer lid by staff parking area MVCAR XCUT		\$18.20
21	3	1	4	SW bld Music : pass green donation box pass at irrigation control box across from Stop sign MVCAR		\$65.00
22	3	0	3	SW bld Music : pass green donation box pass irrigation control box across from Stop sign MVCAR		\$36.40
23	2	1	4	SW bld Music : pass green donation box across from LED school sign before Stop sign MVCAR		\$48.75

No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
24	3	2	1.5	SW bld Music : pass green donation box across from LED school sign before Stop sign MVCAR CRACK		\$30.55
25	4	2	4	SW bld Music : pass green donation box across from LED school sign before Stop sign MVCAR		\$97.50
26	8	0	3	SW bld Music : at sewer lid across from LED school sign before Stop sign MVCAR XCUT OG		\$97.50
27	3	0	1	SW bld Music : at sewer lid across from LED school sign before Stop sign MVCAR XCUT		\$12.35
28	5	0	1	SW bld Music : at sewer lid by from LED school sign by Stop sign MVCAR XCUT		\$20.15

No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
29	14	0	3	SW bld Music : at sewer lid by from LED school sign by Stop sign MVCAR XCUT		\$170.95
30	3	0	1.5	SW bld Music : pass sewer lid by from LED school sign by Stop sign MVCAR XCUT		\$18.20
31	4	0	3	SW bld Music : pass sewer lid by from LED school sign by Stop sign MVCAR XCUT OG		\$48.75
32	6	1	1.5	SW bld Music : pass student entrance gate across from classroom M-3 before No Parking sign JUMP MVCAR CRACK		\$42.90
33	0	0	0	RR bld Music : pass student entrance gate across from classroom M-3 before No Parking sign Heavily cracked		DO NOT FIX




No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
34	2	0	7	SW 2450 Grant St bld Music : pass student entrance gate across from classroom M-3 at No Parking sign MVCAR PARALLELCUT		\$57.20
35	4	0	4	SW bld Music : pass student entrance gate across from classroom M-3 at No Parking sign MVCAR ATCURB		\$65.00
36	0	0	0	RR bld Music : pass student entrance gate across from classroom M-3 by No Parking sign Heavily cracked		DO NOT FIX
37	2	0	2	SW bld Music : pass classroom M-3 pass No Parking sign before vehicle gate MVCAR		\$16.25
38	5	0	4	SW bld Music : pass classroom M-3 pass No Parking sign before vehicle gate at GB MVCAR		\$81.25

No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
39	2	0	2	SW bld Music : pass classroom M-3 pass No Parking sign before vehicle gate at GB MVCAR CRACK		\$16.25
40	4	0	5	SW bld Music : pass classroom M-3 pass No Parking sign by vehicle gate at GB MVCAR CRACK		\$81.25
41	3	0	1.5	SW bld Music : pass classroom M-3 before English bld by vehicle gate pass GB MVCAR XCUT		\$18.20
42	2	0	1	SW bld Music : pass classroom M-3 before English bld by vehicle gate pass GB MVCAR XCUT LCUT		\$8.45
43	2	0	2.5	SW bld Music : pass classroom M-3 before English bld by vehicle gate pass GB MVCAR LCUT		\$20.15

No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
44	2	0	3.5	SW bld Music : pass classroom M-3 before English bld by vehicle gate pass GB MVCAR CRACK		\$28.60
45	3	0	2	SW bld Music : pass classroom M-3 before English bld at vehicle gate pass GB MVCAR		\$24.70
46	2	0	2.5	SW bld English : at LP548 by vehicle gate before bulletin board MVCAR		\$20.15
47	3	0	4	SW bld English : pass LP548 pass vehicle gate at bulletin board MVCAR		\$48.75
48	0	0	0	ATTN bld English : pass LP548 pass vehicle gate at bulletin board damage slab		DO NOT FIX






No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
49	3	0	6.5	WW bld English : by bld entrance by Ac unit across from Admin bld JUMP PARALLELCUT		\$79.30
50	4	0	7	WW bld English : by bld entrance by Ac unit across from Admin bld		\$113.75
51	5	0	3	WW bld Music : at Room M-2 doorway across from English bld before Science bld JUMP ASPCUT		\$61.10
52	0	0	0	ATTN bld Science : at garden area across from Homemaking bld by Ac unit Locked area		DO NOT FIX
53	3	1	6	WW bld English : at ramp between English bld Admin bld by Ac unit JUMP ASPCUT		\$97.50






No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
54	5	2	6	WW bld English : at ramp between English bld Admin bld by Ac unit ASPCUT		\$170.95
55	3	0	2.5	SW bld English : by bld entrance across from gym area before Admin bld JUMP MVCAR		\$30.55
56	2	0	1.5	SW bld English : by bld entrance across from gym area before Admin bld MVCAR PARALLELCUT		\$12.35
57	4	0	11.5	SW bld English : pass bld entrance across from gym area by Admin bld MVCAR ASPCUT		\$187.20
58	5	0	15.5	SW bld English : pass bld entrance across from gym area by Admin bld MVCAR CURBCUT		\$314.60






No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
59	5	1	10.5	SW bld Administration : by side entrance pass English bld at steps MVCAR ASPCUT		\$256.10
60	4	3	2.5	SW bld Administration : by side entrance pass English bld at steps MVCAR ASPCUT		\$70.85
61	6	0	30.5	SW bld Administration : before Admin bld entrance pass crosswalk before LP547 MVCAR ATCURB DANGER		\$743.60
62	2	0	3	SW bld Administration : before Admin bld entrance pass crosswalk before LP547 MVCAR		\$24.70
63	2	0	4.5	SW bld Administration : by Admin bld entrance pass crosswalk at LP547 MVCAR		\$36.40

No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
64	3	0	2	SW bld Administration : by Admin bld entrance pass crosswalk at LP547 MVCAR LCUT		\$24.70
65	4	0	3.5	SW bld Administration : by Admin bld entrance pass crosswalk at LP547 MVCAR LCUT ATCURB		\$57.20
66	4	0	1.5	SW bld Administration : by Admin bld entrance pass crosswalk by LP547 MVCAR		\$24.70
67	3	0	9	SW bld Administration : by Admin bld entrance pass crosswalk by LP547 MVCAR		\$109.85
68	0	0	0	ATTN bld Administration : by Admin bld entrance at ramp by LP547 sunken brick area		DO NOT FIX






No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
69	4	0	27	SW bld Administration : by Admin bld entrance by ramp by LP547 MVCAR ATCURB DANGER		\$438.75
70	2	0	4.5	SW bld Administration : by Admin bld entrance by ramp at steps MVCAR		\$36.40
71	6	0	58	SW bld Administration : pass Admin bld entrance pass ramp by steps MVCAR ATCURB DANGER		\$1,413.75
72	3	1	8.5	SW bld Administration : pass Admin bld entrance pass ramp by steps MVCAR		\$138.45
73	5	0	10	SW bld Administration : at LP24 across from heater room stadium entrance MVCAR ATCURB		\$203.45






No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
74	0	0	0	RR bld Art : at bulletin board across from stadium entrance before bld entrance Heavily crackcd		DO NOT FIX
75	7	0	22	SW bld Art : pass bulletin board across from stadium entrance by bld entrance at sewer lid MVCAR ATCURB DANGER		\$625.95
76	6	3	7	SW bld Art : pass bulletin board across from stadium entrance by bld entrance at sewer lid MVCAR CRACK		\$256.10
77	2	0	7.5	SW bld Art : pass bld entrance pass sewer lid at CCWD utility box MVCAR		\$61.10
78	2	0	4	SW bld Art : pass bld entrance pass sewer lid at CCWD utility box MVCAR PARALLELCUT		\$32.50

No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
79	0	0	0	RR bld Administration : by admin office entrance by green bench before heater room area JUMP lifted over 2in		DO NOT FIX
80	8	2	12	WW bld Administration : by admin office entrance by green bench before heater room area ASPCUT		\$487.50
81	9	0	11	WW bld Administration : by admin office entrance by green bench by heater room area ASPCUT XCUT		\$402.35
82	2	0	5	WW bld Administration : by admin office entrance by green bench by heater room area XCUT		\$40.95
83	3	0	2.5	WW bld Administration : by admin office entrance by service window by heater room area		\$30.55

No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
84	4	2	4	WW bld Administration : by admin office entrance by service window by heater room area CRACK		\$97.50
85	6	0	7	WW bld Administration : pass admin office at service window at heater room area ASPCUT		\$170.95
86	6	0	2.5	WW bld Administration : pass admin office at service window at heater room area ASPCUT		\$61.10
87	6	0	11.5	WW bld Administration : pass admin office at service window at heater room area ASPCUT		\$280.15
88	5	0	17	WW bld Administration : pass admin office by service window pass heater room area ASPCUT		\$345.15

No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
89	3	2	16.5	WW bld Administration : pass admin office by Romaine Hall entrance by Staff lounge entrance JUMP		\$335.40
90	4	0	7	WW bld Administration : pass admin office by Romaine Hall entrance at Ac units XCUT		\$113.75
91	3	0	8	WW bld Administration : pass admin office by Romaine Hall entrance at Ac units XCUT		\$97.50
92	5	0	7	WW bld Administration : pass admin office by Romaine Hall entrance at Ac units		\$142.35
93	3	0	5	WW bld Administration : pass admin office by Romaine Hall entrance at Ac units		\$61.10






No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
94	2	0	8.5	WW bld Administration : by High school plaque pass Romaine Hall entrance at Ac units		\$68.90
95	4	0	12	WW bld Administration : by High school plaque pass Romaine Hall entrance at Ac units		\$195.00
96	4	1	16	WW bld Administration : by High school plaque pass Romaine Hall entrance at Ac units		\$325.00
97	2	0	8	WW bld Administration : by High school plaque at office handicap entrance across from library		\$65.00
98	3	0	12	WW bld Administration : by High school plaque at office handicap entrance across from library		\$146.25

No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
99	5	0	4.5	WW bld Administration : by High school plaque at office handicap entrance across from library		\$91.65
100	2	0	5	WW bld Administration : by High school plaque at office handicap entrance across from library		\$40.95
101	3	0	5	WW bld Administration : by High school plaque by office handicap entrance at tree across from library CRACK		\$61.10
102	4	0	5	WW bld Administration : by High school plaque by office handicap entrance at tree across from library CRACK		\$81.25
103	3	0	3.5	WW bld Administration : by High school plaque by office handicap entrance at tree across from library CRACK		\$42.90




No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
104	2	0	8	WW bld Administration : by High school plaque by office handicap entrance at tree across from library CRACK		\$65.00
105	3	0	11.5	WW bld Administration : by High school plaque pass office handicap entrance by tree across from library		\$140.40
106	2	0	5	WW 2450 Grant St bld Administration : pass High school plaque by library entrance at bulletin board		\$40.95
107	2	0	10.5	WW bld Administration : pass High school plaque by library entrance at bulletin board		\$85.15
108	4	0	5	WW bld Administration : at treasurer window pass High school plaque across from library entrance across from bulletin board CRACK		\$81.25





No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
109	12	9	8	WW bld Administration : at teasurer window pass High school plaque across from library entrance across from bulletin board OG		\$682.50
110	2	0	1.5	WW bld Administration : at teasurer window pass High school plaque across from library entrance across from bulletin board XCUT		\$12.35
111	5	0	13.5	WW bld Administration : at teasurer window pass High school plaque across from library entrance across from bulletin board XCUT		\$274.30
112	2	0	2	WW bld Administration : at teasurer window pass High school plaque across from library entrance across from bulletin board CRACK		\$16.25
113	2	0	10.5	WW bld Administration : by teasurer window pass High school plaque by library entrance by bulletin board		\$85.15






No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
114	2	0	4.5	WW bld Administration : pass High school plaque at library entrance at bulletin board LCUT		\$36.40
115	3	0	8	WW bld Administration : pass High school plaque at library entrance at bulletin board LCUT XCUT CRACK		\$97.50
116	2	0	4	WW bld Administration : pass High school plaque at library entrance at bulletin board XCUT CRACK		\$32.50
117	4	0	4	WW bld Administration : by treasurer window across from library area before steps		\$65.00
118	2	0	12.5	WW bld Administration : pass treasurer window pass library area by steps at room IMC		\$101.40






No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
119	13	0	59	WW bld Administration : by school plaque by Romaine Hall by electrical utility box JUMP		\$3,116.10
120	10	0	21	WW bld Administration : by school plaque by Romaine Hall by electrical utility box		\$853.45
121	2	0	1.5	WW bld Administration : by school plaque by Romaine Hall pass electrical utility box XCUT		\$12.35
122	2	0	2	WW bld Administration : by school plaque by Romaine Hall pass electrical utility box XCUT		\$16.25
123	2	1	9.5	WW bld Administration : by school plaque by Romaine Hall pass electrical utility box		\$115.70






No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
124	4	1	2.5	WW bld Administration : pass school plaque by Romaine Hall across from center plaza area CRACK		\$50.70
125	9	0	12.5	WW bld Administration : pass school plaque by Romaine Hall across from center plaza area		\$456.95
126	3	0	3	WW bld Administration : pass school plaque by Romaine Hall across from center plaza area		\$36.40
127	3	0	6	WW bld Administration : at library side entrance by Romaine Hall across from center plaza area		\$73.45
128	3	1	7	WW bld Administration : at library side entrance by Romaine Hall across from center plaza area		\$113.75






No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
129	2	0	9.5	WW bld Cafeteria : by Romaine Hall by center plaza area at picnic table area JUMP		\$77.35
130	2	0	4.5	WW bld Cafeteria : by Romaine Hall by center plaza area by snack bar area		\$36.40
131	2	0	8.5	WW bld Cafeteria : by Romaine Hall by center plaza area at snack bar area by tree		\$68.90
132	7	0	66	WW bld Academic : across from classroom 51 at center plaza area by picnic table area by cement bench area JUMP ASPCUT		\$1,877.20
133	4	0	6.5	WW bld Academic : across from classroom 51 at center plaza area by picnic table area by cement bench area		\$105.95






No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
134	2	0	10	WW bld Academic : across from classroom 51 at center plaza area by picnic table area by cement bench area		\$81.25
135	3	0	11.5	WW bld Academic : across from classroom 51 at center plaza area by picnic table area by cement bench area		\$140.40
136	2	0	3	WW bld Academic : across from classroom 51 at center plaza area by picnic table area by cement bench area		\$24.70
137	3	0	10	WW 2450 Grant St bld Academic : across from classroom 51 at center plaza area by picnic table area at cement bench area		\$122.20
138	3	1	2	WW bld Academic : across from classroom 52 at center plaza area by storm drain at cement bench area		\$32.50

No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
139	2	0	5.5	WW bld Academic : across from classroom 52 at center plaza area by storm drain at cement bench area		\$44.85
140	6	0	105.5	WW bld Academic : across from classroom 53 at center plaza area across from lockers at cement bench area ASPCUT		\$2,571.40
141	3	0	11.5	WW bld Academic : across from classroom 53 at center plaza area across from lockers at cement bench area		\$140.40
142	3	0	5	WW bld Academic : across from classroom 53 at center plaza area by storm drain at cement bench area		\$61.10
143	4	3	2	WW bld Academic : across from classroom 53 at center plaza area by storm drain at cement bench area		\$57.20






No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
144	3	0	21	WW bld Academic : across from classroom 54 at center plaza area across from lockers at cement bench area		\$256.10
145	3	1	2	WW bld Academic : across from classroom 55 at center plaza area across from stage area at cement bench area		\$32.50
146	4	0	15	WW bld Academic : across from classroom 55 at center plaza area across from locker area at cement bench area		\$243.75
147	2	0	7	WW bld Academic : across from classroom 55 at center plaza area across from locker area at cement bench area		\$57.20
148	2	0	14	WW bld Academic : across from classroom 56 at center plaza area across from locker area at cement bench area		\$113.75

No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
149	2	0	15	WW bld Academic : across from classroom 56 at center plaza area across from locker area at cement bench area		\$122.20
150	2	1	5	WW bld Academic : pass classroom 56 at center plaza area by stage area by cement bench area		\$61.10
151	4	3	5	WW bld Shops : by stage area by cement bench area across from classroom 5		\$142.35
152	2	0	4	WW bld Shops : pass stage area by cement bench area at Electrical utility box by classroom 4		\$32.50
153	3	0	5	WW bld Shops : pass stage area at cement bench area across from classroom 3		\$61.10


No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
154	2	0	9.5	WW bld Shops : pass stage area at cement bench area across from classroom 3		\$77.35
155	3	0	16.5	WW bld Shops : before bathroom area by cement bench area across from classroom 2		\$200.85
156	2	0	22	WW bld Shops : by bathroom area at cement bench area pass classroom 2		\$178.75
157	3	0	10.5	WW bld Shops : by bathroom area by drinking fountain area by cement bench area pass classroom 2		\$128.05
158	3	0	6.5	WW bld Shops : across from bathroom area by cement bench area pass classroom 2		\$79.30






No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
159	3	0	3	WW bld Shops : across from bathroom area by cement bench area before bulletin board PATCH		\$36.40
160	3	0	10	WW bld Shops : by classroom 7 by ramp at electrical utility box ASPCUT		\$122.20
161	4	0	16.5	WW bld Shops : by classroom 8 by ramp pass electrical utility box ASPCUT		\$268.45
162	3	0	6	WW bld Art : at Career center room at ramp across from snack bar area JUMP ASPCUT		\$73.45
163	6	0	4.5	WW bld Art : pass Career center room at ramp access to elevator across from kitchen JUMP ASPCUT		\$109.85






No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
164	6	0	16.5	WW bld Art : pass bld front entrance by storm drain across from stadium area JUMP MVCAR ASPCUT DANGER		\$402.35
165	6	0	7.5	WW bld Art : pass bld front entrance by storm drain across from stadium area MVCAR		\$182.65
166	0	0	0	RR bld Art : by emergency fire house attachment by storm drain across from classroom P1 lifted over 2in		DO NOT FIX
167	3	0	21.5	WW bld Art : at classroom P2 across from Career center back door by across from Ac unit JUMP MVCAR DANGER		\$261.95
168	3	0	8.5	WW bld Art : at classroom P1 across from Career center back door by across from Ac unit MVCAR DANGER		\$103.35




No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
169	5	0	11.5	WW bld Art : by classroom P1 across from Career center back door by across from Ac unit MVCAR ASPCUT DANGER		\$233.35
170	4	0	22	WW bld Art : pass classroom P1 by handicap parking area at water utility box MVCAR ASPCUT		\$357.50
171	3	0	18	WW bld Art : by classroom P1 by handicap parking area at across from classroom P8 MVCAR ASPCUT		\$219.70
172	4	0	5.5	WW bld Art : by classroom P3 at Ac units at across from classroom P6 ASPCUT		\$89.70
173	4	0	10	WW bld Art : by classroom P1 by handicap parking area at by classroom P8 JUMP MVCAR ASPCUT		\$162.50



No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
174	4	0	12.5	WW bld Art : by classroom P6 by storm drain at by Ac unit JUMP ASPCUT		\$203.45
175	4	1	22	WW bld Art : by classroom P8 by student exit gate by bench area JUMP ASPCUT		\$447.20
176	7	0	12	WW bld Art : by classroom P9 by student exit gate at bench area ASPCUT		\$341.25
177	3	0	6.5	WW bld Art : by classroom P8 by student exit gate by bench area		\$79.30
178	4	0	22	WW bld Art : by classroom P6 by water utility lid by storm drain ASPCUT		\$357.50

No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
179	14	0	4.5	SW bld Gym : at vehicle exit gate at pedestrian exit gate at storm drain JUMP MVCAR LCUT		\$256.10
180	10	0	9	SW bld Gym : at vehicle exit gate at pedestrian exit gate at storm drain MVCAR LCUT ATCURB DANGER		\$365.95
181	3	0	6	SW bld Gym : at vehicle exit gate at pedestrian exit gate at storm drain MVCAR CRACK		\$73.45
182	6	0	3	SW bld Gym : by vehicle exit gate by pedestrian exit gate at storm drain MVCAR ATCURB DANGER		\$73.45
183	6	5	6	SW bld Gym : by vehicle exit gate by pedestrian exit gate at storm drain MVCAR DANGER		\$268.45






No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
184	5	0	18	SW bld Gym : pass vehicle exit gate by Sraff parking area before Gym bld MVCAR ATCURB DANGER		\$365.95
185	3	0	4.5	SW bld Gym : pass vehicle exit gate by Sraff parking area before Gym bld MVCAR		\$54.60
186	5	0	7.5	SW bld Gym : pass vehicle exit gate by Sraff parking area before Gym bld MVCAR ATCURB DANGER		\$152.10
187	2	1	6.5	SW bld Gym : pass vehicle exit gate by Sraff parking area before Gym bld MVCAR		\$79.30
188	7	0	3	SW bld Gym : pass vehicle exit gate by Sraff parking area before Gym bld MVCAR		\$85.15






No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
189	6	2	6	SW bld Gym : pass vehicle exit gate by Sraff parking area before Gym bld MVCAR		\$195.00
190	4	0	9	WW bld Gym : at Science bld by classroom Lab1 pass LP JUMP ASCUT		\$146.25
191	4	0	17	WW bld Gym : at Dance studio doorway at ramp across from Science lab bld JUMP		\$276.25
192	7	0	18	WW bld Gym : at gym entrance at handicap access sign across from staff parking area JUMP MVCAR XCUT		\$512.20
193	5	0	44	WW bld Gym : at gym entrance at handicap access sign across from staff parking area MVCAR XCUT ASCUT		\$893.75



No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
194	0	0	0	ATTN bld Gym : across from gym entrance by irrigation control boxes across from staff parking area PATCH		DO NOT FIX
195	5	0	2	WW bld Gym : across from front office area by flagpole area by Mt. Diablo High sign JUMP MVCAR XCUT		\$40.95
196	5	0	4.5	WW bld Gym : across from front office area by flagpole area by Mt. Diablo High sign MVCAR XCUT		\$91.65
197	3	0	3	WW bld Gym : across from front office area by flagpole area by Mt. Diablo High sign MVCAR		\$36.40
198	5	2	3	WW bld Gym : across from front office area by flagpole area by Mt. Diablo High sign MVCAR CRACK		\$85.15




No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
199	0	0	0	ATTN bld Gym : across from front office area by flagpole area by Mt. Diablo High sign broken slab		DO NOT FIX
200	0	0	0	ATTN bld Gym : across from front office area by flagpole area by Mt. Diablo High sign broken slab		DO NOT FIX
201	7	1	19	WW bld Gym : across from front office area at flagpole area at Mt. Diablo High sign		\$617.50
202	3	2	1.5	WW bld Gym : across from front office area at flagpole area at Mt. Diablo High sign CRACK		\$30.55
203	4	2	4.5	CSW bld Music : at LED school sign by Stop sign by storm drain JUMP MVCAR		\$109.85

No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
204	5	0	4	CSW bld Music : by LED school sign pass Stop sign pass storm drain MVCAR OG		\$81.25
205	2	0	3	CSW bld Music : by LED school sign pass Stop sign pass storm drain MVCAR		\$24.70
206	5	0	3.5	CSW bld Music : pass LED school sign pass Stop sign pass storm drain MVCAR		\$70.85
207	3	0	3	CSW bld Music : pass LED school sign pass Stop sign across from hospital sign MVCAR XCUT		\$36.40
208	2	0	1.5	CSW bld Music : pass LED school sign pass Stop sign across from hospital sign MVCAR XCUT		\$12.35

No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
209	3	0	1.5	CSW bld Music : pass LED school sign pass Stop sign across from hospital sign MVCAR XCUT		\$18.20
210	6	0	2.5	CSW bld Music : pass LED school sign pass Stop sign across from hospital sign MVCAR XCUT		\$61.10
211	5	0	3	CSW bld Music : pass LED school sign pass Stop sign across from hospital sign MVCAR		\$61.10
212	14	6	4.5	CSW bld Music : at LP2243 pass Stop sign across from hospital sign MVCAR		\$365.95
213	3	0	3.5	CSW bld Music : at LP2243 pass Stop sign across from hospital sign MVCAR		\$42.90

No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
214	5	0	2.5	CSW bld Science : pass LP2243 by End Road Work sign across from hospital sign MVCAR		\$50.70
215	2	0	3	CSW bld Science : at traffic signal utility box by sewer lid across from hospital sign MVCAR		\$24.70
216	3	0	4	CSW bld Science : pass traffic signal utility box by bus stop across from hospital sign MVCAR		\$48.75
217	5	0	3.5	CSW bld Science : pass traffic signal utility box at bus stop before traffic lights MVCAR		\$70.85
218	3	0	4	CSW bld Science : by One way sign by bus stop before traffic lights MVCAR		\$48.75

No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
219	3	0	3	CSW bld Science : by One way sign by bus stop before traffic lights MVCAR		\$36.40
220	2	1	4	CSW bld Science : pass One way sign pass bus stop by traffic lights MVCAR		\$48.75
221	4	0	3.5	CSW bld Science : at traffic lights by utility box across from bld entrance MVCAR		\$57.20
222	4	1	4	CSW bld Science : pass traffic lights pass utility box at Restaurant Parking sign MVCAR PATCH		\$81.25
223	4	0	4	CSW bld Science : pass traffic lights pass utility box by Restaurant Parking sign MVCAR PATCH		\$65.00

No.	Max Ht. (1/8 of In.)	Min Ht. (1/8 of In.)	Length (Feet)	Description	Before Picture	Cost
224	6	1	4	CSW bld Science : pass traffic lights pass utility box by Restaurant Parking sign MVCAR		\$113.75
225	2	1	4	CSW bld Science : pass traffic lights pass utility box by Restaurant Parking sign MVCAR		\$48.75
226	5	0	3	CSW bld Science : pass traffic lights pass utility box pass Restaurant Parking sign MVCAR		\$61.10